


Safety Instructions

1. The **C130** is designed for indoor use only.
2. **DO NOT** expose the product to a high humidity environment. It may damage the LED grow lights used with the product.
3. **DO NOT** cover or place objects over the **C130**. It should not be contained in an airtight space.

Mechanical Dimensions



Required Tools



Philips Screwdriver

Kessil Lighting

1689 Regatta Blvd
Richmond, CA 94804
www.kessil.com



Copyright © 2011 All Rights Reserved

KESSIL C130 SPECTRAL CARRIER

User Manual

Package Contents

- | | | | |
|-----------------------|------|----------------------------|------|
| a. Base Housing | (1x) | g. U-Bracket | (1x) |
| b. Base Cover | (1x) | h. Multi-port Power Outlet | (1x) |
| c. Hanging Bar | (4x) | i. Cable Tie | (1x) |
| d. Insulating Bushing | (6x) | j. Screw M4X12 | (4x) |
| e. Hex Post | (1x) | k. Screw M4X8 | (3x) |
| f. Triangle Hook | (2x) | | |




Installation Guide

1. Remove contents from package.
2. Insert AC adapters (power supplies) of the grow lights into the **Base Housing (a)**, and align into slots.



3. Screw the **Hex Post (e)** into the **Base Housing (a)**.




4. Secure the **U-Bracket (g)** with one **Screw M4x8 (k)**.




5. Plug the power supplies of the grow lights into the **Multi-port Power Outlet (h)**, using the **Cable Tie (i)** to secure.



6. Insert the **Insulating Bushing (d)** into the **Base Housing (a)**. Adjust the length of the **Hanging Bars (c)**. Place the **Base Cover (b)** over the unit.



7. Secure **Screws (j, k)**.



8. Loop the **Triangle Hooks (f)** through holes at the ends of the unit. Mount the LED grow light using its own screw(s) through the holes on the **Hanging Bars (c)**.



9. Hang **C130 Spectral Carrier** one to two feet above object to be illuminated.

